


Learn



Outline the Scene 	Incident	Site hoarding blown over in inclement weather.
	Subject	Temporary Works
	Incident Date	12-10-2021
	Business Unit	Fletcher Living - Canterbury

What happened



Contractors were undertaking site remediation works. The weather at time was wet with strong and gusting winds. A perimeter fence (consisting of fence panels covered with scrim, with M10 anchors through 2 x fencing clamps, secured to the base of concrete bollards "deadman") had been installed on the foot path (paving slabs) on the edge of the site boundary which was being cut for the remediation works. As the wind increased the fence and "deadman" blew into the site with the fence panel striking a worker on the shoulder. The worker did not sustain any significant injuries as a result of the incident.



We believe all injuries are preventable, here are some questions to help us learn



1. Have you considered site hoarding as temporary works?
2. Are your Team trained in Temporary Works?
3. Does your Temporary Works procedure consider independent review and or check?
4. Once installed is there a process to inspect, monitor and record?

For more information, please contact;

Name and role title: **Jamie Miller EHS Manager Canterbury**
Email and phone details: jmiller@frl.co.nz 021 991 469