



Outline the Scene	Incident	Failure of safety net
	Subject	Fall from height
	Incident Date	15-08-2022
	Business Unit	Fletcher Living – Central Branch

What happened?

A contractor stood on the safety net to get on top of the next wall. The safety net came undone, and the worker fell through the gap and onto the floor below. No serious injuries were sustained. Initial assessment indicates that the bracket was overfilled, and the nets were not tied together where they overlap.



We believe all injuries are preventable, here are some questions to help us learn

	 Are the controls installed correctly? Are the controls used as intended and contractors aware of the limitations on the controls? Have we considered if there are safer methods to complete the work?
--	---

